

Little Diversified Architectural Consulting, Inc. 615 South College Street, Suite 1600 Charlotte, North Carolina 28202

Phone: 704-561-5123 Fax: 704-561-8700

Re: Tractor Supply Company - Senoia Village

Senoia, GA

January 17, 2024

## **BUILDING MATERIAL PERCENTAGES OF FAÇADE AREA NARRATIVE**

## FRONT FAÇADE:

Total Façade Area -	+/- 2,801 s.f.
Brick (w/o brick infill panels) – Brick In-Fil Panels – Silver/Grey Corrugated Panels – Cornice (EIFS) – Storefront (entry door and glass) –	+/- 1,270 s.f. = approx. 86% - 88% +/- 200 s.f. = approx. 6% - 8% +/- 951 s.f. = approx. 32% - 34% +/- 160 s.f. = approx. 4% 6% +/- 220 s.f. = approx. 6% - 8%
LEFT SIDE FAÇADE:	
Total Façade Area –	+/- 3,103 s.f.
Brick (w/o brick infill panels) – Brick In-Fil Panels – Silver/Grey Corrugated Panels – Silver/Grey Standing Seam - Cornice (EIFS) –	+/- 2,688 s.f. = approx. 86% - 88% +/- 150 s.f. = approx. 3% - 5% +/- 56 s.f. = approx. 1% - 3% +/- 60 s.f. = approx. 1% - 3% +/- 149 s.f. = approx. 4% 6%
RIGHT SIDE FAÇADE:	
Total Façade Area –	+/- 3,103 s.f.
Brick (w/o brick infill panels) – Brick In-Fil Panels – Silver/Grey Corrugated Panels – Silver/Grey Standing Seam - Cornice (EIFS) – Storefront (entry door and glass) –	+/- 2,576 s.f. = approx. 82% - 84% +/- 100 s.f. = approx.2% - 4% +/- 100 s.f. = approx. 2% - 4% +/- 60 s.f. = approx. 1% - 3% +/- 149 s.f. = approx. 4% - 6% +/- 118 s.f. = approx. 2% - 4%
REAR FAÇADE:	
Total Façade Area –	+/- 2,092 s.f.
Smooth Face Painted Block – Silver/Grey Corrugated Panels – Roll- Up Door -	+/- 1,832 s.f. = approx. 86% - 88% +/- 160 s.f. = approx. 6% - 8% +/- 100 s.f. = approx. 3% - 5%

<sup>&</sup>quot;Since no building plans have been created, these percentages are approximate. The permitted set of building plans once approved and permitted by the city of Senoia will control"

**END OF NARRATIVE** 

Fax: 704.561.8700