

Application for Certificate of Appropriateness

Date Received 6/2/2	Application No.:		
Address of Subject Propert	121 Baggarly Way, Senoia, GA 30276		
Applicant:	Thomas A and Karen Devenney Nolan		
E-Mail:	tom.nolan@cfacorp.com_		
Applicant Mailing Address	116 Baggarly Way, Senoia, GA 30276		
Applicant Phone(s):	678-458-0179		
Applicant's relationship to Other	ne owner: Owner_X_ Architect: Contractor/Builder		
*******	************************	*****	
Owner(s):	same		
E-Mail:	same		
Owner(s) Mailing Address	same		
Owner(s) Telephone Numb	r: same		
********		*****	
Approximate age or date o project:	construction of the primary structure on the property and any secondary structures affected 113 Years	by this	
Nature of work (check all t	at apply):		
New construction X Demo	tion Addition Moving a building Other building changes		
	andscaping Fence/Wall Other environmental changes		
Sign installation or replace	ent 🗆 Other 🗓		
Description of Work:			

ORIGINAL REQUEST: December 2022

Add ½ story to story to update home to 3 bedroom / 2 baths, add front porch, rebuild 2 chimneys, and replace patio are with a back deck.

Front porch across front of home will create a Southern Colonial architectural historic style, typical of homes built in the late 19th / early 20th century in the south.

New windows and other material will be HPC compliant.

REVISED REQUEST: June 2023

As selective demolition began, it became apparent that existing home had significant mold and structural issues. Structural engineer was engaged and recommended "that the best and correct course of action with regard to this structure is to completely demolish existing structure to ground level and build a new structure that meets current code requirements." See attached letter from Robert Winslow, P.E., dated May 25, 2023.

Request is to scrape and rebuild home per the previously approved design, updating plans to meet current building codes.

This form must be completed in its entirety before the Planning Department accepts it. The form must be accompanied by supporting documents (plans, material, color samples, photos, etc.). All documents submitted in hard copy must also be

submitted in digital form (.pdf format). All relevant ite which lacks any of the required attachments shall be de-	ms from the applic etermined incomple	ation checklist must be addressed te and will not be accepted.	d. An application
Applicant Form Com	Date	June 97 , 2023	

This checklist was created to help applicants prepare a complete application. Omissions and inaccurate information can lead to deferrals and/or denials of applications. Please review the checklist with the project's architect, designer, or builder. All items will not be applicable to all projects. New construction will involve all categories.

Please address questions regarding applicability to your project to the Assistant City Manager, Jeff Fisher at 770-599-3679 or ifisher@senoia.com. Applicants are also referred to the City of Senoia website, https://www.senoia.com/documents. Please bring completed application to Sharon Casey at city hall or if you would like, you may email it to her at scasey@senoia.com. Her direct number is 770-328-3275.

I have reviewed the "Design Guidelines for the City of Senoia" Y N

I have reviewed applicable zoning codes regarding lot coverage, garage sizes, stream buffers Y N

1. General

- a. Label all drawings with the address of the site, owners' name, and contact phone number.
- b. Number all drawings.
- c. Include a graphic scale on reductions.
- d. Date all revisions.
- e. Indicate all unverified numbers with +/- signs
- e. Include photos of the existing condition of the property.

2. Site Plan (existing and proposed) to include

- a. Topographical plan with significant trees sized and located;
- b. Setback compared to adjacent houses (ask surveyor to show corners of adjacent houses);
- c. Distance between houses;
- d. Façade width to finished face of material;
- e. Grading and elevations across site;
- f. Dirt removal or regrading if more than 18";
- g. Tree protection plan;
- h. Tree removal and replacement plan

3. Driveways and Walkways

- a. Location and relationship to house;
- b. Width;
- c. Material;

- d. Curb cut and apron width
- 4. Fences & Retaining Walls
 - a. Placement on lot;
 - b. Height of fence or wall. If retaining wall, height on both sides;
 - c. Material;
 - d. Railing if necessary
 - 5. Elevations and Floor Plans << Indicate all unverified numbers with +/- signs>>
 - a. Plans for all floors (drawn to scale, 1/4"=1' preferred);
 - b. House orientation on site plan;
 - c. Scalable elevations for front, rear, left, right;
 - d. Height, grade to ridge;
 - e. Streetscape comparison showing heights of two flanking houses on each side;
 - f. Height from grade to first floor level at all four corners;
 - g. Height from grade or finished floor line to eaves at all four corners;
 - h. Ceiling heights of each floor, indicating if rough or finished;
 - i. Height of space between the ceiling and finished floor above;
 - j. Two people of 5'-6" and 6' height shown;
 - k. Landscaping plan

6. Additions

- a. Placement shown on elevations and floor plan;
- b. Visibility from rights-of-way and paths;
- c. Photos of all facades;
- d. Design proportioned to main house;
- e. Landscaping plan;
- f. Materials and their combinations

7. Roof Plan

- a. Shape and pitch of roof;
- b. Roofing material;

- c. Overhang;
- d. Louvers and vents;
- e. Chimney height and material

8. Dormers

- a. Construction details provided;
- b. Shape and size of dormer (show dimensions on drawings);
- c. Overhang;
- d. Size of window(s), with nominal size of sash (show dimensions on drawings)

9. Skylights

- a. Profile;
- b. Visibility from right-of-way;
- c. Material (plastic lens or glass);
- d. Shown in plan and elevation to scale

10. Façade

- a. Consistency in style;
- b. Materials and their combinations

brick size and color

stone type and color

fiber-cement (e.g. Hardieplank) or wood siding

shake or shingle

other

- c. Height of foundation at corners;
- d. Ceiling heights comparable to area of influence: basement, first floor, second floor;
- e. Detailing: soldier course, brackets, fascia board; water table;
- f. Height from grade to roof ridge;
- g. Dimensions, proportions and placement of windows, doors

11. Entrance

- a. Height and width of door;
- b. Design of door (e.g. 6-panel, craftsman);
- c. Material of door;
- d. Overhang;
- e. Portico height;
- f. Size and height of columns or posts;
- g. Railing

12. Windows

- a. Consistent with original as well as the area of influence;
- b. Size and proportion similar to original;
- c. Pane orientation and size similar to original;
- d. Type (e.g. double hung, casement);
- e. Fenestration on walls visible from right-of-way;
- f. Simulated divided light (SDL) or true divided light (TDL): location of muntins between the glass, behind the glass or permanently affixed on exterior;
- g. Material of window and any cladding;
- h. Width of muntins compared to original (show dimensions on drawings);
- i. Shutters or canopies
- j. Dimensions of windows and doors.

13. Materials

- a. Show all materials and label them on drawings;
- b. Provide samples of brick or stone;
- c. Provide samples if new or unusual materials

14. Garages / Accessory Buildings

- a. Visibility from street;
- b. Placement on site;
- c. Scale, style appropriate for house;
- d. Show dimensions on drawings;
- e. Materials;
- f. Square footage appropriate for lot size;
- g. Garage door size and design
- h. Show height from grade to eaves and to top of roof

Xound Ch

5-7-23

Applicant Signature

Date

Grounds for Demolition: The resource constitutes a hazard to the safety of the public or the occupants.

Attached, please find:

- Letter from Robert Winslow, P.E., dated May 25, 2023
- Pre-approved plans (elevation and floor plans) from original project
- Site plan of existing structure to be demolished attached (reference survey)
- · Photographs of existing structure

Architectural / historical data

- Date of construction: 1910
- Architectural Style: Regional vernacular built by craftsmen in the area and typical of other homes built in Senoia in the late 19th / early 20th century
- Historic photographs: N/A
- · Name of original owner / builder / developer: Unknown
- Building timeline Post original construction, it is estimated that the house was remodeled in 1953 with additions, much of which led to the moisture intrusion, creating issues identified in letter from Robert Winslow, P.E.
- Original building materials: House is constructed of wood framing, clapboard siding, and sat on a rock / rubble foundation
- Historic information: Known previous residents included the Mr. and Mrs. Hancock and the Sewell family

May 25, 2023

Tom and Karen Nolan 116 Baggarly Way Senoia, GA 30276

Regarding:

121 Baggarly Way

Senoia, GA 30276

Subject:

Structural Inspection of Historic Residential Structure

Mr. and Mrs. Nolan:

On April 17, 2023, at the request of your designer, I performed an inspection at the above referenced structure. The purpose of the inspection was to evaluate the existing building foundation and floor system for structural soundness and to assess these components for continued use with regard to the proposed remodel of the structure.

During this inspection, I made observations from the building crawl space and exterior and I observed the following:

- The floor framing and foundation of the structure appeared to include many components of original construction, however had been heavily modified at some point in time at which additions had been made to the building.
- The floor framing in the addition areas could best be described as irregular with regard to spacing and geometry and did not appear to sufficiently support the structure.
- The floor framing materials were not consistent in size or material type
- The floor framing for the addition areas had been constructed in a manner in which it potentially compromised the structural integrity of the original structure.
- Vertical deflections (sags and dips) were visible in the framing.
- Areas of the framing were being supported by posts / piers that appeared to have been added to resolve floor settlement some time after the addition had been made.
- The exterior foundation was constructed of CMU blocks.
- · No evidence of reinforcement (rebar, etc.) or grout in the CMU foundation was observed.
- The structure did not appear to be tied horizontally or vertically to the foundation.
- Upon observing holes that were dug adjacent to the foundation on each side of the structure, the foundation walls did not appear to be set on a concrete footing.

Based on these observations, it was my professional opinion that the existing walls and foundation were not safe for occupancy and that at a minimum the foundation walls and piers should be replaced with new foundations that were properly set on concrete footings and included reinforcement and ties per current code. It was also my opinion that further observation should be performed on the existing wall framing once demolition of surface materials inside the structure had been completed.

On May 23, 2023, I returned to the structure to perform an inspection of the vertical and ceiling framing components, as the interior finish materials had been removed. During this inspection I observed the following:

- Wall framing consisted of materials that varied in dimension and spacing.
- Large portions of the framing had extensive termite damage and rot.
- · Large portions of the framing and sheathing were covered with mold spores.
- The interior of the structure had a strong odor of mold and wood decay.
- Exposed framing at the previous addition revealed that said addition had compromised the integrity of the
 original framing.
- Exposed sections of ceiling framing revealed that the structure had experienced prolonged periods of water intrusion, likely from a leaking roof, that had damaged the integrity of the structural components.
- The floor in nearly every room was not level, with sagging areas that confirmed previous observations from under the structure.


Based on my observations of the structure, it is my professional opinion that the existing structure is not safe for occupancy. Furthermore, required repairs to make the building safe for occupancy and code compliant are likely of a financial magnitude that is of greater value than that of the structure itself. Additionally, the existing structural components were compromised when previously modified incorrectly and have deteriorated to a state that they are no longer adaptable for rehabilitation.

I summary, it is my finding and professional opinion that the best and correct course of action with regard to this structure is to completely demolish the existing structure to ground level and build a new structure that meets current code requirements.


If you have any questions, please contact me.

Regards,


Robert Winslow, PE



Front Skelby



and the Plans with the trend of the party of



abipatant.

BK:5278 PG:777-779

D2021008343

FILED IN OFFICE CLERK OF COURT 03/19/2021 01:47 PM CINDY BROWN, CLERK SUPERIOR COURT COWETA COUNTY, GA

Edge & Kimbell Law, LLC 503 Commerce Drive Peachtree City, GA 30269

File No.: PTC-21-2218 Parcel ID: E02-0009-004

9035938284 7067927936 PARTICIPANT IO

Return to:

roar D. C. pair.

PT-61 038-2021-002068

REAL ESTATE TRANSFER TAX PAID: \$178.50

LIMITED WARRANTY DEED

STATE OF GEORGIA, COUNTY OF FAYETTE

THIS INDENTURE, Made the 19th day of March, 2021 between

Winnie Merle Hancock.

of the State of Georgia, as party of the first part, hereinafter called Grantor and

Thomas A. Nolan and Karen Devenney Nolan, as joint tenants with right of survivorship,

'as parties of the second part, hereinafter called Grantees (the words "Grantor" and "Grantee" to include their respective heirs, successors and assigns where the context requires or permits).

WITNESSETH that: Grantor, for and in consideration of the sum of ONE HUNDRED SEVENTY EIGHT THOUSAND FIVE HUNDRED AND 00/100 Dollars (\$178,500.00) AND OTHER VALUABLE CONSIDERATION, in hand paid at and before the sealing and delivery of these presents, the receipt whereof is hereby acknowledged, have granted, bargained, sold, eliened, conveyed and confirmed, and by these presents do grant, bargain, sell, alien, convey and confirm unto the said Grantees, all that tract or parcel of land:

See Exhibit "A" Attached Hereto and Made a Part Hereof

commonly known as 121 Baggarly Way, Sensia, GA 30276

SUBJECT to all zoning ordinances, easements, and restrictions of record insofar as the same may lawfully affect the abovedescribed property.

TO HAVE AND TO HOLD the said tract or parcel of land, with all and singular the rights, members and appurtenances thereof, to the same being, belonging or in anywise appertaining, to the only proper use, benefit and behoove of the said Grantees forever in FEB SIMPLE.

AND THE SAID Grantor will warrant and forever defend the right and title to the above described property unto the said Grantees against the claims of all persons owning, holding or claiming by, through or under the said Grantor.

File No.: PT 121,2218

Limited Warranty Deed

Page 1 of3

BK:5278 PG:778

IN WITNESS WHEREOF, the Grantor have signed and Signed sealed and delivered in the presence of:	d sealed this deed, the day and year above written. Winne Mall Manager Attorney in fact
Will Hibrill	Winnie Merle Hancock by Gale Goldenberg, Attorner-In-Fact
Notery Public John A. Kimbell My Commission Expires: February 23, 2025 SEA (.:	
are of the	A. KIMANA



File No.: PTC-21-2218

Limited Warranty Doed

Page 2 of3

EXHIBIT "A" LEGAL DESCRIPTION

All that tract or parcel of land lying and being in the City of Senoia, Georgia, to-wit: One house and lot on Baggarly Way (Formerly known as Jones Ave.), in the Town of Senola, Coweta County, Georgia, fronting West on Baggarly Way 94 feet running back even width 61 feet, bound on North by R.C. Sullivan, East by Eugene Harris, South by John W. Cooper and West by said Baggarly Way.

This is the same property as deeded by Mrs. Daniel, Bt Al to R.S. Sewell on the th day of March 1937 and Recorded Clerk's Office Superior Court, Newman, Coweta County, Georgia in Book 33, Folio 551 on March 13, 1937

Also:

All that tract or parcel of land situate, lying and being in the City of Senoia, Coweta County, Georgia and being a ten foot wide strip more particularly described as follows:

Begin on the East side Baggarly Way at the Southwest corner of the tract obtained by grantors by Warranty Deed from Nell B. Sullivan of record in Deed Book 843, Page 433, Office of the Clerk, Coweta County Superior Court, and run thence Northeasterly along the North line of grantee sixty-one feet, more or less, to the Northeast comer of the tract obtained by grantee from R.S. Sewell by Warranty Deed of record in Deed Book 287, Page 402, aforesaid records; thence run Northwesterly ten feet along a line parallel to the East side of Baggerly Way to a point; thence run southwesterly sixty-one feet, more or less, along a line parallel to the North line of grantee to the East side of Baggarly Way; thence run Southeasterly along the East side of Baggerly Way ten feet to the Point of Beginning of the tract herein conveyed.

Also


All that tract or parcel of land situate, lying and being in the City of Senoia, Coweta County, Georgia, identified as Tract 2, all as shown on plat of property dated December 4, 2000 prepared by W. W. Flowers, Jr., Georgia Registered Land Surveyor for Saundra Frank, said plat of record in Plat Book 72, Page 199, Office of the Clerk, Coweta County Superior Court, reference to which plat is here by made for a more particularly description of Tract 2 described herein.

Tax ID#: E02-0009-004

Subject to any Basements or Restrictions of Record

Limited Warranty Dead

File No.: PTC-21-2218







Front Western Elevation



Side Southern Elevation





Rear Eastern Elevation



Side Northern Elevation